

BROOKSIDE LABORATORIES, INC.

** WATER ANALYSIS REPORT **

Western Golf Properties
1 Spectrum Pointe Dr #310
Lake Forest, CA 92630

File Number: 80046
Date Received: 6/30/2025
Date Reported: 7/1/2025

Submitted By: Soil and Water Consulting

Lab Number	1587
Sample Location	CAMARILLO SPRINGS GC
Sample Description	IRRIGATION WATER HOLE #17

pH	8.03
Hardness (ppm)	905.43
Hardness (grains/gal)	52.95
Conductivity (mmhos/cm)	2.19
Sodium Adsorp. Ratio	3.11
Adjusted SAR	8.94
Adjusted RNa	3.71
pHc	6.52
Residual Sodium Carbonate (RSC)	-8.56

		(ppm)	meq/l	lbs/ac in
Calcium	(Ca)	134.86	6.73	30.59
Magnesium	(Mg)	138.12	11.36	31.33
Potassium	(K)	3.30	0.08	0.75
Sodium	(Na)	215.07	9.35	48.78
Iron	(Fe)	< 0.10		
Total Alkalinity	(CaCO ₃)	479.20		108.68
Carbonate	(CO ₃)	0.00		
Bicarbonate	(HCO ₃)	581.17	9.53	131.81
Hydroxide	(OH)	0.00		
Chloride	(Cl)	314.54	8.87	71.34
Sulfur as	(S04)	362.44	7.55	82.20
Salt Concentration	(TDS)	1399.04		317.30
Boron	(B)	0.27		0.06

Manganese	(Mn)	0.992		0.225
Copper	(Cu)	< 0.020		
Zinc	(Zn)	< 0.040		
Aluminum	(Al)	< 0.200		

Cation/Anion Ratio	NA
--------------------	----

NO ₃ -N (ppm)	0.45
Total P (ppm)	1.27

Reviewed by:

Jackie Brackman