



BROOKSIDE LABORATORIES, INC.
GEOTECHNICAL DIVISION
200 WHITE MOUNTAIN DRIVE
NEW BREMEN, OH 45869

**** PHYSICAL ANALYSIS REPORT ****

Tucson Country Club
2950 N. Camino Principal
Tucson, AZ 85715

File Number: 34998

Date Received/Started : 4/27/2018
Date Completed/Reported: 5/1/2018

Submitted By: Soil and Water Consulting

Lab Number	0508
Sample Description	USGA MIX 3XW PIONEER
Sample Condition	<u>XX</u> Normal ___ Other (see comments)

Method References

ASTM F1632
ASTM F1647 - Method A
ASTM F1815

D Values

** D10: 0.18
** D60: 0.46
** Coefficient of Uniformity: 2.57

*Reported values are an average of duplicated analysis

** NON A2LA ACCREDITED
* *This report may only be reproduced in its entirety.*
* *These results represent the sample submitted only.*



Geotechnical
(Putting Green Materials)
Certificate Number: 736.01

**** PHYSICAL ANALYSIS REPORT ****

Tucson Country Club
2950 N. Camino Principal
Tucson, AZ 85715

File Number : 34998
** Date of Analysis **
Start Date : 4/27/2018
Completed : 5/1/2018

Submitted By: Soil and Water Consulting Reviewed by:

Tiffany Albers

Lab Number 0508
Sample Description USGA MIX
3XW
PIONEER

Particle Size Analysis

Clay	<.002mm	%	0.5
Silt	.002mm - .05mm	%	1.1
Sand	.05mm - 2.00mm	%	98.4
Gravel	> 2.0mm	%	0.0

Org Mat 360 deg C (LOI)	0.18
-------------------------	------

Sand Fractions

Sieve Size		% Retained
#	mm	
10 - 2.0	Fine Gravel	0.0
18 - 1.0	Very Coarse Sand	3.3
35 - .500	Coarse Sand	28.5
60 - .250	Medium Sand	47.2
100 - .150	Fine Sand	15.2
140 - .106	Very Fine Sand	3.3
270 - .053	Very Fine Sand	0.9

Soil Moisture Measurements

Saturated Conductivity in/hr	31.3
------------------------------	------
