




BROOKSIDE LABORATORIES, INC.
GEOTECHNICAL DIVISION
200 WHITE MOUNTAIN DRIVE
NEW BREMEN, OH 45869

**** PHYSICAL ANALYSIS REPORT ****

Tucson Country Club
2950 N. Camino Principal
Tucson, AZ 85715

File Number: 34998

Date Received/Started : 8/3/2022
Date Completed/Reported: 8/4/2022
Date Issued: 8/4/2022

Submitted By: Soil and Water Consulting

Lab Number	1675
Sample Description	WCS&G PHX

Sample Condition	☐ Normal	☒ Other (see comments)
------------------	---------------------------------	--

Method References

ASTM C136

D Values

** D15: 3.39
** D90: 8.67
** Coefficient of Uniformity: 2.55

*Gravel Sample

** NON A2LA ACCREDITED

* *This report may only be reproduced in its entirety.*

* *These results represent the sample submitted only.*



Geotechnical
(Putting Green Materials)
Certificate Number: 736.01

**** PHYSICAL ANALYSIS REPORT ****

Tucson Country Club
2950 N. Camino Principal
Tucson, AZ 85715

File Number : 34998
** Date of Analysis **
Start Date : 8/3/2022
Completed : 8/4/2022

Submitted By: Soil and Water Consulting Reviewed by:

Lab Number 1675
Sample Description WCS&G PHX

GRAVEL FRACTIONS % Retained
Sieve Size (mm)

12.5	0.0
9.5	0.8
6.35	34.8
4.75	30.2
2.36	33.8
2.0	0.1
1.0	0.1
< 1.0	0.2
