



BROOKSIDE LABORATORIES, INC.
GEOTECHNICAL DIVISION
200 WHITE MOUNTAIN DRIVE
NEW BREMEN, OH 45869

**** PHYSICAL ANALYSIS REPORT ****

Tucson Country Club
2950 N. Camino Principal
Tucson, AZ 85715

File Number: 34998

Date Received/Started : 6/26/2023
Date Completed/Reported: 6/27/2023
Date Issued: 6/27/2023

Submitted By: Soil and Water Consulting

Lab Number	1541
Sample Description	WCS+G GRAVEL
Sample Condition	☐ Normal ☒ Other (see comments)

Method References

ASTM C136

D Values

** D15: 2.77
** D90: 8.14
** Coefficient of Uniformity: 2.94

*Gravel Sample

** NON A2LA ACCREDITED
* This report may only be reproduced in its entirety.
* These results represent the sample submitted only.



Geotechnical
(Putting Green Materials)
Certificate Number: 736.01

**** PHYSICAL ANALYSIS REPORT ****

Tucson Country Club
2950 N. Camino Principal
Tucson, AZ 85715

File Number : 34998
** Date of Analysis **
Start Date : 6/26/2023
Completed : 6/27/2023

Submitted By: Soil and Water Consulting Reviewed by:

Lab Number 1541
Sample Description WCS+G
GRAVEL

GRAVEL FRACTIONS % Retained
Sieve Size (mm)

12.5	0.0
9.5	0.2
6.35	22.7
4.75	25.6
2.36	44.1
2.0	0.9
1.0	2.1
< 1.0	4.4
