

BROOKSIDE LABORATORIES, INC.

** WATER ANALYSIS REPORT **

Los Robles Greens
299 South Moorpark Road
Thousand Oaks, CA 91361

File Number: 80417
Date Received: 6/30/2025
Date Reported: 7/1/2025

Submitted By: Soil and Water Consulting

Lab Number	1586
Sample Location	IRRIGATION WATER
Sample Description	HOLE #14 FAIRWAY

pH	7.67
Hardness (ppm)	474.50
Hardness (grains/gal)	27.75
Conductivity (mmhos/cm)	1.13
Sodium Adsorp. Ratio	1.74
Adjusted SAR	3.67
Adjusted RNa	1.91
pHc	7.29
Residual Sodium Carbonate (RSC)	-6.56

		(ppm)	meq/l	lbs/ac in
Calcium (Ca)		75.79	3.78	17.19
Magnesium (Mg)		69.26	5.70	15.71
Potassium (K)		2.10	0.05	0.48
Sodium (Na)		87.11	3.79	19.76
Iron (Fe)		< 0.10		
Total Alkalinity (CaCO ₃)		148.60		33.70
Carbonate (CO ₃)		0.00		
Bicarbonate (HCO ₃)		177.78	2.91	40.32
Hydroxide (OH)		0.00		
Chloride (Cl)		111.32	3.14	25.25
Sulfur as (SO ₄)		330.70	6.89	75.00
Salt Concentration (TDS)		723.84		164.17
Boron (B)		0.06		0.01

Manganese (Mn)	< 0.020
Copper (Cu)	< 0.020
Zinc (Zn)	< 0.040
Aluminum (Al)	< 0.200

Cation/Anion Ratio	NA
--------------------	----

NO ₃ -N (ppm)	0.63
Total P (ppm)	< 0.20

Reviewed by:

Jackie Brackman